

9PL01884GV
20-11124

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL01884GV

| | | | | | | | |
|--|---|---|--|------------------------------------|--|--|--|
| Document Number Override | | Primary Crash Document # | | Agency Crash Number | | Investigating Officer/Deputy OFFICER K. YEAGER | |
| Crash Date 09/15/2020 | | Crash Time 99:99 | | Date Arrived 09/15/2020 | | Time Arrived 04:50 PM | |
| Date Notified 09/15/2020 | | Time Notified 04:46 PM | | Total Units 01 | | Total Injured 00 | Total Killed 00 |
| <input type="checkbox"/> On Emergency | <input checked="" type="checkbox"/> Hit and Run | <input type="checkbox"/> Lane Closure | | <input type="checkbox"/> Work Zone | | <input type="checkbox"/> Trailer or Towed | <input type="checkbox"/> Reporting Threshold |
| <input type="checkbox"/> Government Property | | <input type="checkbox"/> Active School Zone | | School Bus Related NO | | Tags | |
| <input type="checkbox"/> Reportable | | Crash Type PRIVATE PROPERTY/PARKING LOT | | | | <input type="checkbox"/> Amended | <input type="checkbox"/> Secondary Crash |

Description

| | |
|---------|---|
| Diagram | Reconstruction By |
| | Photos By K.YEAGER |
| | Additional Information PHOTOS |

☒ I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 09-15-2020 AT APPROXIMATELY 1646 HOURS I WAS DISPATCHED TO THE WALGREENS PARKING LOT FOR A REPORT OF A HIT AND RUN MINOR ACCIDENT. I ARRIVED ON SCENE AND MADE CONTACT WITH THE VEHICLE OWNER WHO WAS IDENTIFIED AS RACHAEL. RACHAEL STATED THAT SHE HAD BEEN WORKING AT WALGREENS ALL DAY AND WHEN HER SHIFT ENDED SHE WENT OUT TO HER CAR AND THAT IS WHEN SHE NOTICED THE DAMAGE. IT IS UNKNOWN WHAT TIME DURING THE DAY THE DAMAGE WOULD HAVE OCCURRED, AND THERE IS NO CAMERA FOOTAGE AVAILABLE DUE TO THE LOCATION HER VEHICLE WAS PARKED IN IS A BLIND SPOT FOR CAMERA COVERAGE. RACHAEL'S VEHICLE SUSTAINED MINOR SCUFFING AND SCRATCHING ON THE REAR DRIVER SIDE QUARTER PANEL, AND REAR DRIVERS SIDE DOOR. THIS IS ALL THE INFORMATION I HAVE AT THIS TIME.

9PL01884GV
20-11124

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

| | | |
|---|--------------------------------------|-----------------------------------|
| PARKING LOT MAIN ST/ STH23 EB LOT 1100 (OTHER 1100) IN THE CITY OF REEDSBURG IN SAUK COUNTY | Latitude 43.531865522 | Longitude -89.994162529 |
| | X Coordinate 258060.484375 | Y Coordinate 4824236.5 |
| | Structure Type OTHER | |

Crash Scene

| | | | |
|---|--|---|---------------|
| First Harmful Event MOTOR VEH IN TRANSPORT | | First Harmful Event Location UNKNOWN | |
| Manner of Collision 03 - FRONT TO REAR | | Light Condition DAYLIGHT | |
| Road Surface Condition(s) DRY | | Roadway Factor(s) NONE | |
| Environment Factor(s) NONE | | | |
| Weather Condition(s) CLEAR | | | |
| Animal Type | | Relation To Trafficway NON TRAFFICWAY - PARKING LOT | |
| Crash Classification - Location PUBLIC PROPERTY | | Crash Classification - Jurisdiction NO SPECIAL JURISDICTION | |
| Tribal Land | | Access Control NO CONTROL | Special Study |
| Within Interchange Area NO | Junction Location NON-JUNCTION | Intersection Type NOT AN INTERSECTION | |

Unit Summary

| | | | | | | |
|------------|---|--|---|----------------------------|--|--|
| UNIT 01 | Unit Status LEGALLY PARKED | | Vehicle Operating As Classification D CLASS | | Unit Type AUTOMOBILE | |
| | Vehicle Type PASSENGER CAR | | | | Operating As Endorsements | |
| | Total Occs 0 | Train/Bus # Recorded | Total # Citations Issued 0 | Total Trailers 0 | Total HazMat Types 0 | |
| | Insurance? YES | Direction Of Travel NOT ON ROADWAY | <input type="checkbox"/> Pre Crash Tire Mark | Speed Limit 05 | Total Lanes 0 | |
| | Most Harmful Event: Collision With PARKED MOTOR VEHICLE | | Special Function NO SPECIAL FUNCTION | | Emergency Motor Vehicle Use NOT APPLICABLE | |
| | Traffic Way PARKING LOT OR PRIVATE PROPERTY | | Traffic Control NO CONTROL | | Traffic Control Inoperative/Missing NO | |
| | Surface Type BLACKTOP (BITUMINOUS) | | Road Curvature UNKNOWN | | Road Grade LEVEL | |
| | Truck Bus or HazMat NO | | | | | |
| | | | | | | |
| | | | | | | |

Vehicle

| | | | | | |
|-----------------------|---|--|---------------------------------------|---------------------|---|
| UNIT VEHICLE 01 | License Plate Number 289WCK | | Plate Type AUT - AUTOMOBILE | St WI | Country of Issuance UNITED STATES |
| | Vehicle Identification Number 1G1BB5SM9G7280172 | | Make CHEVROLET | Year 2016 | Model CRUZE |
| | Color SIL - SILVER (ALUMINUM) | | Body Style SD - SEDAN | | Bus Use |
| | Initial Contact Point 08 - LEFT SIDE REAR | | Vehicle Damage | | |
| | Extent Of Damage MINOR DAMAGE | | 08 - LEFT SIDE REAR | | |
| | | | | | |

9PL01884GV
20-11124

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

| | | | |
|------|---------|---|---|
| UNIT | VEHICLE | Towed Due To Damage NOT TOWED | Vehicle Removed By OWNER |
| | | What Driver Was Doing LEGALLY PARKED | Vehicle Factors |
| | | Driver Prior Action Other | NOT APPLICABLE |
| | | Driver Actions NO CONTRIBUTING ACTION | |
| UNIT | 01 | Owner Name RACHAEL ESTELLE BOWSER | Owner Address 139 MAPLE ST REEDSBURG, WI 53959 , US |
| | | Sequence Of Events | |
| | | 01 | Event PARKED MOTOR VEHICLE |
| | | 02 | Event MOTOR VEH IN TRANSPORT |
| UNIT | 03 | Event | |
| | | Event | |
| | | Policy Holder | |
| | | 04 | Insurance Company |